COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



PROJECT

: SOUTH EAST TRANSIT BUS TUNNEL-SECTION 2

ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95

BOREHOLE NO	:	226
SHEET	:	1 OF 1
REFERENCE No	:	H8164

		:9	C60117		SURFACE R.L. : 22.24		······	ום	RILL	ER : DALY BROTHERS DRILLING	
JOB	No	:	650302C	N	DATUM : AHD			DATE D	RILL	ED: 28/11/97	
O DEPTH (m)	R.L. (m)	AUGER CORE DRILLING CASING OTHER	RQD ()% CORE REC%	SAMPLE	MATERIAL DESCRIPTION	USC	INTACT STRENGTH	DEFECT SPACING (mm) 000- 000- 000- 000-	GRAPHIC LOG	ADDITIONAL DATA AND TEST RESULTS	SAMPLES
	21.24				FILL Red brown, moist, silty clay.					Driller's log only.	-
	20.34				XW TUFF Generally exhibits engineering proper -ties of fine to coase, dry, very dense sity sand.	хw				8,2,30/50 N=>50	SPT
-2			(24) 87		MINOR INTERLAYERS OF CONGLOMERATE, SAND- STONE AND SILTSTONE. BEDDING <10 DEGREES HW - MW zone. DEFECTS MAINLY HORIZONTAL (0-15 degrees) AND OCCASIONAL VERTICAL (85 degrees).	HW HW				Is(50)=0.07MPa	× _
-3	18.72					HW				Is(50)=0.29MPa	×
-4	18.09		(46) 100		MW CONGLOMERATE / AGGLOMERATE GREY TO GREY BROWN, FINE TO COARSE GRAIN -ED MASSIVE PROCLASTIC/SEDIMENTARY ROCK.	MW		<u>.</u>		Is(50)=0.20MPa	×
-5 - 6 - 7 - 8 - 9 - 10					END OF HOLE						
	MARKS	: *!	See att	ach	ed list for defect descriptions.					LOGGED BY	

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.



DEFECT DESCRIPTIONS OF BORELOGS

[FOR GEOTECHNICAL TERMS AND SYMBOLS

REFER FORM BQF 075:191/95]

BOREHOLE NO :	226
SHEET :	1 of 1
REFERENCE NO :	H8164

PROJECT

SOUTH EAST TRANSIT PROJECT - SECTION 2

LOCATION

3949.705E

162332.373N

PROJECT NO

C60117

SURFACE R.L

22.24 DRILLER

DALY BROTHERS PTY

LTD

JOB NO :

650302CN

DATUM

AHD

DATE DRILLED: 28/11/97

DEPTH	DEFECT TYPE	DIP (Degrees)	PLANARITY	ROUGHNESS	APERTURE	WALL ALTERATION	OTHER
3	J	15	Ir	R			Cn
3.32	J	15	Ir	R			Cn
4	J		Ir	R	_		Cn
4.39	J		Ir	R	T		Cn
					_		
				,			
						_	
							
_							
	_						

Abbreviations

	ROUGHNESS	WALL ALTERATIONS			TYPE	OTHER		
R	Rough	FeSt	Iron Stained	J	J Joint		Partly	
Sm	Smooth	W	Weathered	В	Bedding	QZ	Quartz Vein	
SL	Slickensided			BP	Bedding Parting	Co	Completely	
			F	Folliation	In	Incipient		
	PLANARITY		APERTURE		Sheared Zone	SI	Sand Intill	
PI	Planar	С	Closed	WS	Weathered Seam	Н	Horizontal	
St	Stepped	0	Open	CZ	Crushed Zone	V	Vertical	
Un	Undulating	F	Filled	SM	Secondary Mineralisation	CI	Clay Intill	
Cu	Curved	T	Tight	BZ	Broken Zone	Cn	Clean	
Ir	Irregular			HFZ	Highly Fractured Zone			

NOTE: This sheet should be read in conjunction with appropriate Engineering Borelog.

