COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM F:GEOT 017/0-1998

	BOREHOLE	No	:	BH14
	SHEET		:	1 OF 1
1	REFERENCE	No	:	н8914

PROJECT	:	GATTON BYPASS DUPLICATION -	ALLAN STREET L	IND	ERPASS BRIDGE - ABUTM	MENT B	200000000000000000000000000000000000000	
LOCATION	:	EASTING 429196.82, NORTHING	6953468.83					
PROJECT No	:	C60232	SURFACE R.L.	:	107.72	DRILLER	;	DALY BROTHERS PTY LTD
JOB No	:	114/18A/54	DATUM	:	AHD	DATE DRILLED	;	08/06/01

	T		Т	Т-		т т	7	T			
(E)	R.L. (m)	υÑ	RQD				INTACT	DEFECT		ADDITIONAL DATA	
I	(m)		()%		MATERIAL	S.	SINENGIA	SPACING (mm)	LOG	ADDITIONAL DATA	
DEPTH		"EB"		Ш		u u	5	(mm)	2	AND	S II
20		SEST	CORE REC%	SAMPLE	DESCRIPTION	OF			GRAPHIC	TEST RESULTS	SAMPLES
0	107.72	₹000P	RECT	SA		US		28888	GR		SA
-	1				ROAD BASE			\pm			
ţ					50mm asphalt into red gravel road base.			\pm		Driller's record only	
-							1111111	Hilli			-
ţ.	106.92							<u>+:::::</u>			
-1					SANDSTONE			<u>Linini</u>		No recovery 30/30] :
1					FINE TO MEDIUM GRAINED, MASSIVE TO SLIGHTLY LAMINATED, CALCAREOUSLY CEMENTED, SEDIMENTARY ROCK.			<u> </u>		No recovery 30/30 N>50	SPT
-					CEMENTED, SEDIMENTARY ROCK.			<u> </u>			
-					100		111111	<u>-</u> :::::			-
-					HW : No recovery, appears to be very dense silty sand.	HW		<u> </u>			
-2						ĺ		<u>Lililil</u>			
ļ .								<u>tiiiiil</u>			
-											
F	105.14						1 1 1 1 1 1	- : : : :		30/75 	8885 PH 8888
-			1		SANDSTONE	SW	1 - 70			Sittstone pand	
- 3					MW : Pale orange brown to pale grey, medium strength with frequent very high strength SW bands.	MW			388888888888888888888888888888888888888	Siltstone band Is(50)=0.51MPa	x =
F					strength SW bands.	Inw	4				
F					Frequent very coarse quartz and rock				**********	Silstone band	-
-					Frequent very coarse quartz and rock clasts showing conglomerate appearance.	SW				Is(50)≣1:88MPa	8 -
-			(85)		Defects -		Lagra			Conglomerate band	-
-4			100		Drilling induced subhorizontal partings				*******	Conglomerate band Is(50)=0.08MPa	0 -
					(<10 deg).			C.L		Clay seam	
						MW				Is(50)=0.46MPa	
F								-		15(30)-0.46MPa	x _
- 1	102.77				Grading to SW rock with depth.						
-5	102.77				SW		h				Ė
F						611				Is(50)=0.78MPa	×
F	102.14		(100)		Pale grey to white, massive, mainly medium strength.	SW				Is(50)=0.88MPa	0
	102.14	(S)	100		Defects - Nil.		1000		-		
F					END OF HOLE				1		1
-6											
E					-						1
E							1::::::				1
	-						1				7
- 1							111111				1
-7							11111	-			_
E							# # # # # # #				7
El							#######################################			2	4
- 1											7
Ł I							11111				=
- 8	1										4
ĿΙ					5		#				=
Εl							######			1	=
Εl							######			1	7
ĿΙ							11111				=
- 9		$ \cdot $									4
-	1						######				1
Εl					,		11111				4
E 1							11117				7
10						1				1	7
		1111					<u> </u>				

REMARKS :

