COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/



ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95

BOREHOLE	No	:	128
SHEET		:	1 OF 2
REFERENCE	NΩ		н8195

: SOUTH EAST TRANSIT PROJECT-SECTION 1 PROJECT : 2555.257E 163716.087N LOCATION SURFACE R.L.: 16.24 DRILLER: DALY BROTHERS PTY LTD PROJECT No : C60128 20/1/98 JOB No DATUM : AHD DATE DRILLED : INTACT DEFECT ROD R.L. Е ADDITIONAL DATA SPACING STRENGTH HERING ()% (m) MATERIAL (mm) DEPTH AND GRAPHIC SAMPLES rests DESCRIPTION CORE TEST RESULTS 88888 ᅜᅩᅩᄝᅼ REC* ₹88₽ 0 16.24 16.04 PHYLLITE (rock description in remarks) XW Grey to orange brown, mottled. 15.34 30/100 HW 15.14 COT HW : Core stones and rock kernals. M=>50 MW : (35%)Grey brown to blue grey; partly ironsta ining throughout; extensively fratured rockmass along foliation partings; fri-able and fissile along defects. 100 Is(50)=1.41MPa x (74%)2 Major - Joints at 70 deg. - Joints at 10 deg. Minor - Joint at 25-40 deg. 100 Is(50)=1.36MPa Fractures at 10 deg. - foliation partings at 70 deg. (100)3 100 Is(50)=0.57MPa Water Pressure Test from 3.05m to 10.55; WPT = 2uL (76%)100 Pressuremeter Test at 4.50m Is(50)=0.59MPa(35%) MW 100 Pressuremeter Test at 5,00m Is(50)=0.94MPa (33%)100 Is(50)=0.95MPa (53%)100 (72%) 100 Water Pressure Test from (85%) 7.50m to 10.55m; WPT =<1uL Is(50)=0.59MPa х 100 - 8 7.92 SW : Grey brown to blue brown; frequent blue grey argillite bands; bedding mainly at 40-60 degrees; medium to coarse concordant type quartz veins to 20mm. Is(50)=0.71MPa(91%) Is(50)=0.59MPa SW 100 Defects: Major - Foliation partings (40-60 deg) - Joints (30-40 deg.) Minor - Fractures <10 deg. - Joints at 70 deg. Is(50)=1.23MPa х Is(50)=1.44MPa LOGGED BY REMARKS PHYLLITE: GREY GREEN TO BLUE GREY MEDIUM TO COARSE GRAINED FOLIATED META-DISS SEDIMENTARY ROCK. BEDDDING STEEP (90 DEG.), SUBVERTICAL AND, TO 40 DEGREES.



PROJECT

ENGINEERING BORELOG

FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95

: SOUTH EAST TRANSIT PROJECT-SECTION 1

BOREHOLE	No	:	128
SHEET		:	2 OF 2
REFERENCE	No	:	н8195

LOCA	TION	:2	2555.25	7E	163716.087N		٠.						
PROJ	JECT No	:	60128		SURFACE R.L. : 16.2	4			DI	RILLI	ER : DALY BROTHERS PTY LTD		
JOB										LLLI	D: 20/1/98		
_				Τ			T	INTACT	DEFECT		ADDITIONAL DATA		
٤)	R.L. (m)	I I	()%		MATERIAL	2		STRENGTH	SPACING (mm) 0000 0000 0000	GRAPHIC LOG			
DEPTH		 		щ					(11111)	으	AND	ES	
DE			CORE REC%	SAMPLE	DESCRIPTION		Ē :		888	₹	TEST RESULTS	SAMPLES	TESTS
10	6.24	5000	RECT	S,			1	┸╱╌	11111	5		ŝ	픠
- - -			(100)		SW : (As above.).	SW		1			Di		1
_	5.69		100			-	+				Piezometer Tip at 10.45m		=
-					END OF HOLE				‡!!!!!!				1
- - 11									<u> </u>			i	
[ĺ						-
_							١						4
-							1						- 1
- -							١		<u> </u>				ᅼ
-12							١						4
-							١		<u> </u>				4
-							١	4 1 1 1 7					7
Ē							١	4					3
- 13							١						Ⅎ
-							١		<u> </u>				=
-							١						-1
-]
14							1						ᅼ
. 1 3							1		<u> </u>				4
-						1			-				- 1
'- -						1							3
													3
15						1							Ⅎ
'.						1							- 1
_													-
-													=
[-16					•				<u>L</u>				ᅼ
: "													4
Ė													3
									F				=
													4
- 17									‡				4
t.									‡				
-									<u> </u>				-]
Ĺ									<u> </u>				4
18									<u> </u>				4
:									‡				7
									<u> </u>				E
									<u> </u>				4
									‡				#
-19									‡::::::				7
Ė						ŀ			Ī:				=
- -									 				4
:									‡ • • • • •				4
- 20			l	\perp				: : : : : -	<u>†</u>				ᅼ
RI	emarks	P.	lease r	efe	r attached sheet for defect descriptions	:					LOGGED BY		
											DISS		



DEFECT DESCRIPTIONS OF BORELOGS

(FOR GEOTECHNICAL TERMS AND SYMBOLS REFER FORM BQF 075:191/95]

BOREHOLE NO	BH128
SHEET :	1 of 2
REFERENCE NO :	H8195
-	

PROJECT : SOUTH EAST TRANSIT PROJECT - SECTION 1

LOCATION : 2555.257E 163716.087N

PROJECT NO : C60128 SURFACE R.L : 16.24 DRILLER : DALY BROTHERS P/L

JOB NO : DATUM : AHD DATE DRILLED : 15/1/98

DEPTH	DEFECT TYPE	APPRO. DIP ANGLE (deg.°)	PLANARITY	ROUGHNESS	APERTURE	WALL ALTERATION	OTHER
1.30	FP	70	Ir	R	0	-	
2.03	J	20	P	Sm	0		Cl
2.13-2.22	BZ	15 - 60	-		0		
2.35	J	10	St	R	0	PCI/SM	
3.2	FP	75	Ir	R	0		
3.3	J	25	Ír	R			
3.37	J	25	P	Sm	T	CoFeSt	
3.52	J	40	P	Sm	T	CoFeSt	
3.72	J	10	P	Sm	T	CoFeSt	
3.78	J	10	P	Sm	T	CoFeSt	
3.84	J	10	P	Sm	T	CoFeSt	
3.95-4.35	FP	90	P	Sm	Т	P - CoFeSt	Closely Spaced
4.13	J	10	P	Sm	Т	CoFeSt	
4.15	Ĵ	10	P	Sm	Т	CoFeSt	
4.76	Fr	35	Ir	R	0	PFeSt	
4.90	J	70	Ir	R	0		
5.22	J	70	P	S	Т	CoFeSt	
5.23	J	70	P	S	T	CoFeSt	
5.24	Fr	10	Ir	R	0	CoFeSt	

Abbreviations

	ROUGHNESS	W	WALL ALTERATIONS		TYPE	OTHER		
R	Rough	FeSt	Iron Stained	J	Joint	P	Partly	
Sm	Smooth	W	Weathered	В	Bedding	QZ	Quartz Vein	
SL	Slickensided			FP	Foliation Parting	Co	Completely	
				Fr	Fracture	In	Incipient	
	PLANARITY		APERTURE	SZ	Sheared Zone	SI	Sand Infill	
Pl	Planar	С	Closed	WS	Weathered Seam	Н	Horizontal	
St	Stepped	0	Open	CZ	Crushed Zone	V	Vertical	
Un	Undulating	F	Filled	SM	Secondary Mineralisation	CI	Clay Seam	
Cu	Curved	Т	Tight	BZ	Broken Zone	Cn	Clean	
Ir	Irregular			HFZ	Highly Fractured Zone			

NOTE: This sheet should be read in conjunction with appropriate Engineering Borelog.



DEFECT DESCRIPTIONS OF BORELOGS

[FOR GEOTECHNICAL TERMS AND SYMBOLS
REFER FORM BQF 075:191/95]

BOREHOLE NO :	ВН128
SHEET :	2 of 2
REFERENCE NO :	H8195 (b)
_	

PROJECT : SOUTH EAST TRANSIT PROJECT - SECTION 1

LOCATION : 2555.257E 163716.087N

PROJECT NO : C60128 SURFACE R.L : 16.24 DRILLER : DALY BROTHERS P/L

JOB NO : DATUM : AHD DATE DRILLED : 15/1/98

DEPTH	DEFECT TYPE	APPRO. DIP ANGLE	PLANARITY	ROUGHNESS	APERTURE	WALL ALTERATION	OTHER
5.9	FP	40	P	Sm	0	PFeSt	
6	J	40	P	Sm	0	SM	
6.4	Fr	10	St	R	0	CFeSt	
6.54	FP	60	P	R	T		
6.63	FP	70	P	R	T		
6.86	J	40	St	R	Т	CFeSt	
6.9	FP	60	P	Sm			
7.21	J	30	Ir	R	0		
7.31	J	30	Ir	R	Т		
7.36	J	30	Ir	R	Т		
7.05-8.00	FP						Closely spaced
8.15	J	40	P	Sm	Т	CFeSt	
8.2	J	70	P	Sm	Т		
8.25	J	40	P	R	0		
9	FP	60	Ir	Sm	0		
9.55	J	60	P	Sm	Т	CFeSt	
9.58	FP	60	P	Sm	0	CFeSt	
9.95	Fr	40	Ir	R	0	CFeSt	

Abbreviations

	ROUGHNESS	W	ALL ALTERATIONS		ТҮРЕ	OTHER_		
R	Rough	FeSt	Iron Stained	J	Joint	P	Partly	
Sm	Smooth	W	Weathered	В	Bedding	QZ	Quartz Vein	
SL	Slickensided			FP	Foliation Parting	Co	Completely	
		_		F	Fracture	In	Incipient	
	PLANARITY	1	APERTURE	SZ	Sheared Zone	SI	Sand Infill	
Pl	Planar	С	Closed	WS	Weathered Seam	Н	Horizontal	
St	Stepped	0	Open	CZ	Crushed Zone	V	Vertical	
Un	Undulating	F	Filled	SM	Secondary Mineralisation	CI	Clay Seam	
Cu	Curved	T	Tight	BZ	Broken Zone	Cn	Clean	
Ir	Irregular			HFZ	Highly Fractured Zone			

NOTE: This sheet should be read in conjunction with appropriate Engineering Borelog.



