

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "*(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence*". This licence does not apply to the Queensland Government logo or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.


Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

## REPORT ON CONE PENETROMETER TEST

Client **MAIN ROADS**  
Project **GATEWAY UPGRADE NORTH - EARLY WORKS**  
Job Ref.  
Location **E 509318.295, N 6971566.366**  
Chainage  
Sounding **CPTU12A**  
Test Date **23/09/2008**  
Remarks

Project No. **FP5249**  
Surface RL **2.557 m**  
Water Table **0.000 m**  
Start Depth **0.000 m**  
Refusal **5.475 m**

**Water Table was not measured and is assumed.**



Date	<b>22/01/2009</b>	Cone Type	<b>Piezocone</b>
Checked	<i>[Signature]</i>	Cone ID	<b>3832</b>
Signatory	<i>[Signature]</i>	Factor "a"	<b>0.610</b>
		Factor "b"	<b>0.013</b>
		Test Method	<b>Q151-A</b>
		Report No.	<b>FP5249/CPTU12A/Q151-A</b>



Accreditation Number: 2302  
Accredited for compliance  
with ISO/IEC 17025

This document is issued in  
accordance with NATA's  
accreditation requirements.

Program Version 4.03b (32bit)