

COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by McConnell Dowell under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute as follows: "(c) McConnell Dowell 2026, licensed under the CC BY 4.0 Licence, prepared by Insitu Geotech Services". This licence does not apply to logos or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for McConnell Dowell use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.


When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

CONE PENETROMETER TEST RESULT

Golder Associates
Rapid Transit
Gold Coast QLD

CPT2D07b



Job Number : G11-08-02
Test Date : 10/08/2011
DGPS Position : 56 J 0538477, 6906413
DGPS Format : GDA

Tested By : Jeff Chase
Test Class : IGS-1
Checked By : Russell Vincenzi

Cone Number : S15CFIIP.C46
Predrill Depth : 1.20m
Dissipation Tests @ : N/A
Terminated Due To : Abrupt Tilt
(c) McConnell Dowell 2026, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.

Pore Pressure (kPa)

Insitu
Geotech
Services
Pty Ltd

IGS