COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

REPORT ON ELECTRIC FRICTION-SLEEVE CONE PENETROMETER

Test Method No. QMRD 151(B)

PROJECT GATEWAY ARTERIAL

LOCATION E41893.358,N44349.481

JOB No. C138/7270/1

PROJECT No. 2-407

SURFACE R	L 1	.942	m
DATE	18	12/8	99

DATUM

18/12/0	89
---------	----

AHD

...

	(CONE RESISTANCE q _c (MPa)							_	DEPTH (R.L.) (m) 120.0		STRATA DESCRIPTION	FRICTION RATIO F _r (%					(%)
12 1	2	3	4	5	6	7	B	9	12	(m) 0.0	Grapi	DESCRIPTION	0	2	4	6	6	10
1	, ,			·					•	1.942								
									-									
•									• •	1.0		Start					-	
/															5			
ξ										0.942	, 	V. Loose Clayey		5				• •
}								•	-			Sand		\geq				· · -
\mathbf{r}				•								-		٤		• •		
2										2.25					~	>		
				*						-0.31)	Soft - Firm		5				
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~										-		Sandy	1.7	,	•			•
~5		-					-					Clay	1					
	~									-			K			· •	• .	-
$\rightarrow$	>						-						1				• •	-
$\leq$	i.							•	• •	-			<	$\geq$				
$\geq$															<u> </u>			•
2	•												ĺ	<	· · ·	$\leq$	-	
:{	•									4.8						~		
$\mathbf{\mathbf{x}}$										-2.86	5	Stiff	1			, J		
5												Clay					5-1	
2																- 5		
2																	>`	••
}																_		
	>								•				[		5			
<	- -														5			
1			,												_ ک		• •	
$\leq$										7.40				$\sim$		د		
									(	5.458	5	Refusal	1		- •			
													ł					
				r F	t in		1. 1. 1.			**								
-	•			1	Associ		É SCE Testine	12 A	<b>-</b>	-1								
				Au	thorities	ation of Austra	lia 🐔						1					
			Nat	This lab nonal Ass	onatory is location of the rests of	registered of Testing eported he accordance n. This rep ed except	Dy the Authoritie	<b>s</b> .		-					•	<b>.</b>	•- ·	
				been perferences of t	ormed in a	accordano n. This rep	e with its										- ·	
				not be	reproduce	ed except	in Iuli.		· <del>-</del> ··	-				•	• •	: ·	•	·
•								•		-								
	<u></u>		<u>:</u>			•		<b>.</b>		CHECI	۱ ۲.	JBY A	<u>ı                                    </u>	DA	TE	2/	3/90	>
												DRY BAMA	hs	ם חמ		2	3/90	>
(a) State of	00000	cland (D	onartmont	of Trop	nort and	Main Da	ade) 202		V 1 0			D. F. Ma pyright and limitation of	rks	-	c on o			10



## MAIN ROADS Materials Branch, Herston Geomechanical Services

REPORT No.2-4075E 1016

SOUNDING No. CP69BC

REF. No. SE 1016