## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.

A	RI	JP
/ 1		, ,

Trial Pit Log

Job No. 231518-07

**TP03** 

Hole ref

Page 1 of 1

Contractor

Northern Pavement Consultants Pty Ltd

**BHAP Cattle and Frances Creeks Upgrade Project Ground Investigation** 

Ground Level (m) Date 03-Sep-13

Samples & tests			Strata log					
Depth	Sample Type Ref	Test Result	Red. Level	Legend	Depth (Thick- ness)	Description	Stratum	Geology
					(0.07)	Asphalt.		ASPHAL1
-					(0.10) 0.17	Asphalt 2x50mm layers.		ASPHALT
0.20	В				(0.23)	Sandy Clay, trace Gravel, (CL) low plasticity, red brown, sand is fine to coarse, angular, gravel is fine to medium, angular, dry to moist, stiff to very stiff.		
0.21	LB				1			BASE
-	x 2				0.40	Sandy Clay, trace Gravel, (CL) low plasticity, dark red brown, sand is fine to coarse, angular, gravel is fine to medium, angular, moist, stiff.		
0.50	В				(0.30)	anguan, grator o motor motor, anguan, motor, cam		SUB BASE
0.51	LB				0.70			
- - 1.00	B LB x2				(0.50)	Sand with Clay, (SC) fine, brown, clay is low to intermediate plasticity, moist.		ALV
					-	Trial pit completed at 1.2m depth		

## Remarks

Base and sub-base appear to be Deco. Shoulder base is sand with gravel and clay, fine to coarse grained, grey, dry to moist, angular, gravel is fine to medium grained, angular, clay is low plasticity.

Investigation/cluster ref: CFC GI TP


Plant: JBC Site Master Crew: Northern Paving Consultants Backfilled: 03-Sep-13

## Groundwater

No groundwater encountered

Shoring/Support: N/A

Stability: Stable



**TMR** Logged by: Jay Noonan Database check: RAS