## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

## LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

MAIN ROADS REPORT ON ELECTRIC FRICTION-SLEEVE CONE PENETROMETER Materials Branch, Herston Geomechanical Services

Test Method No. QMRD 151(B)

PROJECT GATEWAY ARTERIAL

LOCATION E42958.321,N40153.955

REPORT No.2-4075E 954

SOUNDING No. CP31KC

SURFACE RL 1.784 m

954

AHD

REF. No. SE

DATUM

JOB No.	C13R/7270/1						ЕСТ		. 2-		7 DATE	6/12/89			
	CONE RESISTANCE q <sub>c</sub> (MPa)							1	DEPTH R.L.) (m) 0.0	phic log	STRATR DESCRIPTION	FRICTION			
<u>Ø 1 2</u>	3	4	5	6	7	B	9		1./04	Gr al		824	6	8	10
Γ <u></u>			-					┝	0.4		Start		2		
	, <u>,</u>										Soft - Firm Sandy Clay				
	. 4 -	I										)			
								- H	5.75	, ,					
N have	, / / M			·							Stiff - V. Stiff Sandy Clay	Jun	>	_	
	- Mart	>		This labo onal Asso stralia. T ten perfo rms of re	Associati horitics, pratory is re- pocation of he tests rep immed in acc reproduced of	distered by festing Autorited herein ordance w This report	the thorities n have th its may		9.5 (-7.7	6)	Refusal				
L			<u> </u>			<u> </u>			CHECH			DATE	2/3/9	) <u>)</u> 90.	
									SIGNA	110	D. F. Ma			<u>~0</u>	

(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.