

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by McConnell Dowell under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute as follows: "(c) McConnell Dowell 2026, licensed under the CC BY 4.0 Licence, prepared by Insitu Geotech Services". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for McConnell Dowell use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.


When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

# CONE PENETROMETER TEST RESULT

Golder Associates  
Rapid Transit  
Gold Coast QLD

# CPT202



Job Number : G11-08-02  
Test Date : 10/08/2011  
DGPS Position : 56 J 0538607, 6906213  
DGPS Format : GDA

Tested By : Jeff Chase  
Test Class : IGS-1  
Checked By : Russell Vincenzi

Pore Pressure (kPa)

Cone Number : S15CFIIP.C46  
Predrill Depth : 0.50m  
Dissipation Tests @ : N/A

Terminated Due To : Equipment at Risk  
(c) McConnell Dowell 2026, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.

Insitu  
Geotech  
Services  
Pty Ltd  
**IGS**