## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by Port of Brisbane Pty Ltd under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute Port of Brisbane Pty Ltd and the author as follows: "(c) Port of Brisbane Pty Ltd 2023, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Port of Brisbane Pty Ltd use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <a href="http://qgd.org.au/">http://qgd.org.au/</a>

ARUP	Trial Pit Log	Job No. 249964	Hole ref T-TP22	Page 1 of 1
		Contractor		
			Ground Level (m)	Date
Port Drive Upgrade			5.05	09-Sep-16

Samples & tests			Strata log					
Depth	Sample Type Ref	Test Result	Red. Legend (Thick-ness)  Depth (Thick-ness)		Stratum	Geology		
0.15-0.40	В		4.9	000	(0.15) 0.15/	Silty SAND (SM) fine to medium grained, brown, with organics (roots and vegetation).		TOP
-			4.7	~ \( \) c	(0.25) 0.40	Gravelly SAND (SP) fine to coarse grained, grey-brown, gravel is fine to coarse, sub-rounded to angular, with fines, trace rootlets, dry, dense.  Trial pit completed at 0.4m depth		FILL
-					E	mar pil completed at 0.4m deptin		
- -					-			
-					-			
-			-		_			
-					-			
-			-		-			
-								
-			-		-			
					[			
-					-			
-					-			
					[			
- -								
-					-			
					-			
-					_			
_					<u> </u>			

Remarks

Shovel refusal at 0.4m

Local coords: MGA coords: 516321.47E,6968825.52N Ground level = 5.05mOD Investigation/cluster ref: Main


Plant: 8T Crew: MF Backfilled: 09-Sep-16

Groundwater

No groundwater encountered

Shoring/Support: None

Stability: Stable



Logged by: GCP Database check:

Hole/test made by Contractor but logged by Arup. <<DrawingFileSpec>>