

## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the [Creative Commons Attribution 4.0 Licence](#) (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "*(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup*". This licence does not apply to logos or trademarks.

## **LIMITATION OF LIABILITY**

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database <http://qgd.org.au/>

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.

## TEST PIT RECORD

TP

# TP10

SHEET 1  
OF 1

PROJECT Lang Park Stadium Redevelopment

LOGGED BY VL  
DATE/S 26.10.00

CONTRACTOR BL&T PLANT HIRE EXCAVATION TYPE  
EQUIPMENT TYPE Backhoe LENGTH 3m  
MODEL CAT 428B 4x4 WIDTH 0.7m

GROUND LEVEL approx. RL 9.6m  
LOCATION

EXCAVATION	STRATA			MATERIAL DESCRIPTION	CONDITION		OBSERVATION									
	R.L.	DEPTH	LEGEND		CONSISTENCY											
SAMPLE, TEST, BIT, SUPPORT, ETC.	AHD	m		GROUP SYMBOL	SOIL TYPE Colour, Plasticity, Grain Size, Minor Components	WATER / MOISTURE	CONSISTENCY		SOIL ORIGIN, STRUCTURE, ETC.							
			COHESIVE				NON COHESIVE									
					VS	S	F	ST	VST	LL	VL	LD	MD	DD	VD	
				Sandy Gravelly topsoil layer over silty GRAVEL: with much cobbles and boulders, some broken pieces of pottery												FILL
		1		becoming more clayey, with iron staining and much coarse gravel and cobbles a layer of ash silt and fine to coarse gravel, with much rusted metal pieces, pottery, bottles and glass, some boulders and phyllite.												
				thin layer of clayey material over a dark brown black ashy sand layer, with much rusted metal sheets, pipes, cans and wood fragments												
				wood fragments, wires, glass jars, bottles, rotting odour												
		2														
		3		As above												
		4.00		END TP10 @ 4.0m (limit of excavator)												

NOTES

- 1) No groundwater encountered during excavation.
- 2) Corner of OZ Sport

JOB

12215

BOREHOLE/TEST PIT LANGSEC.GPJ ARUP\_AUS.GDT 10/01/01