COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2022, licensed under the CC BY 4.0 Licence, prepared by Insitu Geotech Services". This licence does not apply to logos or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://ggd.org.au/

This log has been contributed to the Queensland Geotechnical Database with the permission of Insitu Geotech Services.

CONE PENETROMETER TEST RESULT

TMR CPT12 Bruce Hwy Upgrade Section D **Gympie QLD** Sleeve Friction (kPa) 300 3000 0 75 750 1500 2250 0 Depth (m) 5 1111 1111 million and a state of the r e 5 3 10 5 10 Friction Ratio (%) 15 1.5 30 8 60 6 Uncorrected Cone Resistance - qc (MPa) 400 300 500 200 100 Job Number : G15-04-05 Tested By : Russell Vincenzi Pore Pressure (kPa) Test Date : 23/04/2015 Test Category : IGS-1S Checked By : Dave Chapman Test Date : 23/04/2015 DGPS Position : 56 J 0469754, 7102262 DGPS Format : GDA Rig : Esme Cone Number : S15CFIIP.S11101 Predrill Depth : 0.00m Dissipation Tests @ : N/A Insitu S

(c) State of Queensland (Department of Transport and Main Roads) 2022, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.

Dissipation Tests @ N/A Terminated Due To : Lifted Rig

Geotech Services

Pty Ltd