### **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by Insitu Geotech Services under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute Insitu Geotech Services as follows: "(c) Insitu Geotech Services 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to logos or trademarks.

### LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Insitu Geotech Services use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.


Retrieved from the Queensland Geotechnical Database <a href="http://qgd.org.au/">http://qgd.org.au/</a>

This log has been contributed to the Queensland Geotechnical Database with the permission of Insitu Geotech Services.

## **CONE PENETROMETER TEST RESULT**




# **AGS2020-01**



## PORE PRESSURE DISSIPATION TEST RESULT

QLD AGS AGS Exhibition New Farm QLD AGS2020-01 Depth: 13.67m

### Pore Pressure (kPa)



Tested By: Dean Treloar Test Duration: 0 Hours, 39 Minutes Test Date: 10/12/2020

Job No: G20-02-04 Cone: S15CFIIP.S19288

