## **COPYRIGHT NOTICE**

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Transport and Main Roads under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department as follows: "(c) State of Queensland (Department of Transport and Main Roads) 2020, licensed under the CC BY 4.0 Licence". This licence does not apply to the Queensland Government logo or trademarks.

## LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

REPORT ON ELECTRIC FRICTION-SLEEVE CONE PENETROMETER

Test Method No. QMRD 151(B)

GATEWAY ARTERIAL PROJECT

E41950.039,N44326.970 LOCATION


C138/7270/1 JOB No.

PROJECT No. 2-407

Materials Branch, Herston Geomechanical Services REPORT No.2-407SE 1020

MAIN ROADS

SOUNDING No	CP68RL
REF. No. S	GE 1028
DATUM	AHD
SURFACE RL 2.242 m	
DATE	23/1/90



(c) State of Queensland (Department of Transport and Main Roads) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.