COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by Port of Brisbane Pty Ltd under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute Port of Brisbane Pty Ltd and the author as follows: "*(c) Port of Brisbane Pty Ltd 2023, licensed under the CC BY 4.0 Licence, prepared by Arup*". This licence does not apply to logos or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Port of Brisbane Pty Ltd use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

ARU	P	Trial Pit	Log		Job No. 249964	Hole ref F			Page 1 of	Page 1 of 1	
	L				Contractor			1			
Port Drive Upgrade					Ground Level (m) Date 5.25 30-A					6	
Samples & tests S					a log						
	Test Red. Result Leve		Depth (Thick- ness)		Description				Stratum	Geology	
0.10-0.37 B	5	52 X X 0 \((0.10)	Gravelly SAND	Silty SAND (SM) fine grained, grey-brown, with organics (vegetation), slightly mois Gravelly SAND (GW) fine to coarse grained, pale orange, gravel is fine to coarse,				t	TOP FILL	
0.37-0.70 B	4		- (0.27) - 0.37 - (0.33)	Gravelly SAND	soub-rounded to angular, dry, dense. Gravelly SAND (GW) fine to coarse grained, grey to brown-grey gravel is fine to coarse, sub-rounded to angular, with cobbles (0.13m), with silt, dry to slightly moist,						
	4	1.6 0 20	0.70	dense.	sub-rounded to angular, with cobbles (0.13m), with slit, dry to slightly moist,					FILL	
Remarks Shovel refusal at 0.7m					Ground Investig Plant: 8 Crew: N	oords: 51649 level = 5.25 gation/cluster	ref: Main	۷			
Groundwater No groundwater encountere Shoring/Support: None Stability: Stable	ed		⊢ D	2.2 — A	► B 0.75						
Client				С	Logged by: GCP		Database check:				

Hole/test made by Contractor but logged by Arup. <<DrawingFileSpec>> (c) Port of Brisbane Pty Ltd 2023, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.