COPYRIGHT NOTICE

This geotechnical log and its associated data (the Document) is licensed by the Queensland Department of Housing and Public Works under the <u>Creative Commons Attribution 4.0 Licence</u> (CC BY 4.0). When reusing the Document, in whole or in part, please attribute the Department and author as follows: "(c) State of Queensland (Department of Housing and Public Works) 2020, licensed under the CC BY 4.0 Licence, prepared by Arup". This licence does not apply to logos or trademarks.

LIMITATION OF LIABILITY

The CC BY 4.0 Licence contains a comprehensive Disclaimer of Warranties and Limitation of Liability. In addition, please note that this Document was prepared for Departmental use only. Reuse of the Document by anyone for any other purpose could result in error and/or loss. You should obtain professional advice before making decisions based on the contents of the Document.

When reproducing any part of this Document, you must also reproduce this limitation of liability notice in addition to the italicised attribution statement above.

Retrieved from the Queensland Geotechnical Database http://qgd.org.au/

This log has been contributed to the Queensland Geotechnical Database with the permission of Arup.

	ARU Geotechr) Pics		TEST PIT RECORD	TP	TPe	5	SHEET 1 OF 1
· ···	PROJECT Lang Park Stadium Redevelopment						VL 26.10.0	n
	CONTRACTOR EQUIPMENT TYPI MODEL	BL&T PLANT HI E Backhoe CAT 428B 4x4	RE	EXCAVATION TYPE LENGTH 3m WIDTH 0.7m		ROUND LEV		
с.	EXCAVATION	STRATA		MATERIAL DESCRIPTION		CONDI	FION	OBSERVATION
	Sample, test, Bit, support, . etc.	R.L. DEPTH	LEGEND	SOIL TYPE Colour, Plasticity, Grain Size, Minor Components	WATER / MOISTURE	COHESIVE		210.
t		AHD m 호 0.10	<u></u>	TOPSOIL: brown, gravely slit/silty gravel, fine to coarse gravel		Sor 03		TOPSOIL
				Clayey GRAVEL: mottled brown grey and red, high plasticity, fine to medium gravel				FILL
				becoming more grey in colour				
[some cobbles and traces of boulders Silty sandy ashy material with much rust, broken glass bottles and fragments of metal, cables and pottery pieces.	-			-
	-	-3 3.10		As above, with much rust				-
ARUP_AUS.GDT 10/01/01				END TP6 @ 3.1m				-
				-			JOB	-
BOREHOLE/TEST PIT LANG	1 11 11 10 01	oundwater encountered o	luring ex	cavation.				12215

Į

(c) State of Queensland (Department of Housing and Public Works) 2020, CC BY 4.0. Please note copyright and limitation of liability notices on attached cover page.